## **Electric Cover and** Electric Distributor Gene Degirme




Excellent Milling Properties...

## **WORKING PRINCIPLES**

GED

There are various hatches tor the purpose of unloading, loading, transfer between two conveyors, or tor transfer from conveyor to elevator. The use of these hatches are important and must be mounted correctly to reach the desired capacity.







## (in 🖸 f 🎯 🕲 🖸

Genc Degirmen

## **Product Data Sheet**

Туре	Dimensions (mm)					
	А	В	с	D	E	F
GED 2/220	250	430	700	220	220	850
GED 2/270	250	460	740	270	270	900
GED 3/220	220	380	250	220	1170	1120
GED 3/270	270	400	250	270	1170	1120
GED 4/220	220	380	250	220	1270	1140
GED 4/270	270	400	250	270	1270	1140



